

inscopebt

Thermoscan

Thermal Imaging Helps you Detect, Troubleshoot and Fix Problems to Prevent Costly Shutdowns and Outages

Electrical equipment is prone to overheating, items such as circuit breakers, bolted connections, fuses, power distribution systems and most general switchgear in your facilities switchboards. This overheating is a major cause of damage to essential equipment, unfortunately to the naked eye this is often undetectable. With Inscope's Thermal Imaging we are able to make this issue quickly and clearly visible, report on and make any necessary repairs or replacements in a cost effective and timely manor.

For more information or to discuss our Preventative Maintenance Inspections call us today

